LG Phoenix 2 Headphone Jack Replacement

Replace your headphone jack on the LG Phoenix 2 if the sound quality is low or nonexistent.

Written By: Sarah Popp

This document was generated on 2020-11-28 07:12:25 AM (MST).

INTRODUCTION

If you need to install a new headphone jack on your LG Phoenix 2, use this guide to disassemble and replace the damaged part. For this guide you will need a plastic opening tool and a Phillips #000 screwdriver. These steps will be straightforward and easy to follow, but the pieces should be handled with care, so as to not damage or misplace any needed components.

🔧 TOOLS:

- iFixit Opening Tools (1)
- Phillips #0 Screwdriver (1)

This document was generated on 2020-11-28 07:12:25 AM (MST).

Step 1 — Headphone Jack

- Insert a fingernail into the notch on the bottom right corner of the phone.

- Pop off the back cover off of your device.

Step 2

- Insert a fingernail in the notch under the battery.

- Remove the battery.

This document was generated on 2020-11-28 07:12:25 AM (MST).

Step 3

- Insert the opening tool under the bottom cover.

- Pop the bottom cover off.

Step 4

- Remove eight 3mm screws using a Phillips #0 screwdriver.

Step 5

- Insert the opening tool in between the phone screen and the silver trim.

- Pop off the trim.

Step 6

- Insert a screwdriver into the headphone jack.

- Pop out the headphone jack.

This document was generated on 2020-11-28 07:12:25 AM (MST).

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2020-11-28 07:12:25 AM (MST).