iFIXIT

[Nyx Fly II] charging port replacement

charging port replacement only

Written By: @HectorNavarroMX

This document was generated on 2022-03-20 10:19:42 PM (MST).

Page 1 of 3

www.iFixit.com

🔧 TOOLS:

- Tweezers (1)
- xg-50 mechanic solder paste (1)
- Hot Air Rework Station Hakko FR-810 (1)

it should be works correctly.

This document was generated on 2022-03-20 10:19:42 PM (MST).