

Dell Inspiron Mini 1012 Screen Replacement

Step by step instructions on how to locate and...

Written By: sabinabarajas



INTRODUCTION

Step by step instructions on how to locate and remove screws and parts of the device to locate the screen, remove it, replace it with a new one, and put the device back together.



TOOLS:

- Phillips #00 Screwdriver (1)
- Phillips #1 Screwdriver (1)
- Metal Spudger (1)
- Spudger (1)

Step 1 — Screen







- Remove the battery from the device for safety. Slide the two tabs on the bottom of the computer to the unlocked position, and gently lift up the battery.
- Remove the two rubber pieces at the bottom of the screen and remove the screws located behind them.
- Carefully remove the plastic casing from the device.

Step 2








- Remove the four screws on each corner of the screen. Then remove the screws located on the side of the screen.
- Carefully unplug the ribbon on the back of the screen.

Step 3







- Place the new screen onto the device and plug the ribbon in.
- Replace the screws on the side of the screen.

Step 4







- Snap on the plastic screen cover and replace the two screws and the rubber pieces at the bottom
 of the screen.
- Turn the computer over and put the battery back in.

To reassemble your device, follow guide instructions.