



2002-2007 Jeep Liberty Oxygen Sensor Replacement

A video tutorial on how to change the O2 oxygen sensor on a 2002-2007 Jeep Liberty.

Written By: eCuration



INTRODUCTION

If you have a code P0133, its your O2 sensor going bad. Here we are demonstrating on how to remove one.

Follow this video tutorial by YouTuber [NutzAboutBolts](#) to complete the repalcement yourself.

Safety

If this is your first time working on a vehicle read our [safety tips](#) before proceeding.



TOOLS:

- [3/8" Drive Ratchet](#) (1)
- [3/8-Inch Drive Extension Bar](#) (1)
- [Oxygen Sensor Wrench](#) (1)



PARTS:

- [Oxygen Sensor](#) (1)

To reassemble your device, follow these instructions in reverse order.