



LG K10 Earphone jack Replacement

This video shows you how to repair LG K10 broken, doesn't work, not responding headphone jack replacement.

Written By: Witrigs

LG K10

Headphone Jack Repair Guide



INTRODUCTION

This repair guide will teach you how to replace the 3.5 mm auxiliary jack in an LG K10.



TOOLS:

- [iFixit Opening Picks set of 6](#) (1)
- [Tweezers](#) (1)
- [Phillips #00 Screwdriver](#) (1)
- [Spudger](#) (1)



PARTS:

- [LG K10 Headphone Jack replacement](#) (1)

Step 1 — Earphone jack




- Power off the device.
- Remove the back lining

Step 2




- Remove the battery

Step 3



- Unscrew every screw of the bottom of the phone and use guitar picks to remove the plastic frame of the phone

Step 4



- With tweezers remove the headphone jack piece on the motherboard, and insert the new piece in the position of the old one.

Step 5



- Screw in the bottom case.

Step 6



- Insert the battery and back case.

To reassemble your device, follow these instructions in reverse order.